


3M™ Speedglas™ Welding Helmet 9100-QR



| Part No | Description | Part No | Description | Part No | Description |
|--------------|--|--------------|--|--------------|---|
| 06-0100-10QR | Speedglas welding helmet 9100-QR with 9100V welding filter and 3M Hard Hat H-701 | 06-0100-20QR | Speedglas welding helmet 9100-QR with 9100X welding filter and 3M Hard Hat H-701 | 06-0100-30QR | Speedglas welding helmet 9100-QR with 9100XX welding filter and 3M Hard Hat H-701 |



Accessories and consumables

| Part No | Description | Part No | Description | Part No | Description |
|--------------|---|--------------|---|--------------|--|
| 04-0023-02 | 3M hard hat H-701R, white (unvented) | 06-0200-52-B | Part no 06-0200-52, 50/case | 06-0300-54QR | Welding helmet 9100-QR with quick release rail, without welding filter, without hard hat |
| 04-0320-00 | Batteries 2/case | 06-0200-53 | Outside protection plate high temperature, 10/case | 06-0300-55 | Silver front panel 9100 |
| 06-0000-10 | Speedglas welding filter 9100V | 06-0200-53-B | Part no 06-0200-53, 50/case | | |
| 06-0000-20 | Speedglas welding filter 9100X | 06-0400-55 | Battery holder 9100, 2/case | | |
| 06-0000-30 | Speedglas welding filter 9100XX | 06-0400-55-B | Part no 06-0400-55, 10/case | | |
| 06-0000-30i | Speedglas welding filter 9100XXi | 06-0500-56 | Magnification plate 15x | | |
| 06-0200-10 | Inside protection plate 9100V, 5/case | 06-0500-57 | Magnification plate 20x | | |
| 06-0200-10-B | Part no 06-0200-10, 25/case | 06-0500-58 | Magnification plate 25x | | |
| 06-0200-20 | Inside protection plate 9100X, 5/case | 06-0500-59 | Magnification plate 30x | | |
| 06-0200-20-B | Part no 06-0200-20, 25/case | 18-0099-68 | Ear and neck protection in leather | | |
| 06-0200-30 | Inside protection plate 9100XX, 5/case | 06-0014-00QR | Quick release rail for hard hat | | |
| 06-0200-30-B | Part no 06-0200-30, 25/case | 06-0114-00QR | Rail retention parts | | |
| 06-0200-51 | Outside protection plate standard, 10/case | 06-0116-00QR | Pivot cover plate kit | | |
| 06-0200-51-B | Part no 06-0200-51, 50/case | 06-0119-00QR | Distance bar when using welding filters 9100X/9100XX/9100XXi | | |
| 06-0200-52 | Outside protection plate scratch resistant, 10/case | 06-0118-00QR | Ear muff bar for Speedglas welding helmet 9100-QR | | |
| | | 06-0300-52QR | Welding helmet 9100-QR without quick release rail, without welding filter, without hard hat | | |